

Sylvania - Automotive/Metals

Mult_coc25A

Portland CC

Building Type		County	
Community_College		Multnomah	
Street			
12000 Sw 49th Ave			
City	State	Zip	
Portland	OR	97219	
Latitude		Longitude	
45.43662		122.73072	
Tracking Code		Inspection Date	
Miller 2004-05		8/31/2005	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1
Tertiary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9

Sylvania - Automotive/Metals

Final RVS Score

Final Type


Final Score

C1

0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1968	1968	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71667	2	No	No

Plan Irregularities	Vertical Irregularities
None	Yes: Unknown

Falling Hazards	Poor Conditions
Other: Light Cladding	
None	
None	

