

|                   |       |                 |  |
|-------------------|-------|-----------------|--|
| Building Type     |       | County          |  |
| Community_College |       | Multnomah       |  |
| Street            |       |                 |  |
| 12000 Sw 49th Ave |       |                 |  |
| City              | State | Zip             |  |
| Portland          | OR    | 97219           |  |
| Latitude          |       | Longitude       |  |
| 45.43808          |       | 122.73083       |  |
| Tracking Code     |       | Inspection Date |  |
| New Building      |       | 3/1/2007        |  |

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Sylvania - LRC

## Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (&lt;1%)



|                                    |                                   |                                   |                                 |
|------------------------------------|-----------------------------------|-----------------------------------|---------------------------------|
| Enrollment                         | Year Built (Field Verified)       | Year Built (Alt. Source)          | Est. Decade Built               |
| <input type="text"/>               | <input type="text" value="1994"/> | <input type="text" value="1994"/> | <input type="text"/>            |
| Total Area (square ft)             | Number of Stories                 | Basement                          | Pounding Potential              |
| <input type="text" value="65165"/> | <input type="text" value="2"/>    | <input type="text" value="No"/>   | <input type="text" value="No"/> |

|                      |                         |
|----------------------|-------------------------|
| Plan Irregularities  | Vertical Irregularities |
| <input type="text"/> | <input type="text"/>    |
| <input type="text"/> | <input type="text"/>    |
| <input type="text"/> | <input type="text"/>    |

|                      |                      |
|----------------------|----------------------|
| Falling Hazards      | Poor Conditions      |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |