

# Sylvania - Sculpture Studio

Mult\_coc34A

Portland CC

Building Type Community_College	County Multnomah	
Street 12000 Sw 49th Ave		
City Portland	State OR	Zip 97219
Latitude 45.43882	Longitude 122.73081	
Tracking Code New Building	Inspection Date 3/1/2007	

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sylvania - Sculpture Studio

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sylvania - Sculpture Studio

Mult\_coc34A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2004	2004	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	