

Sylvania - South Classroom B.

Mult_coc35A

Portland CC

Building Type		County	
Community_College		Multnomah	
Street			
12000 Sw 49th Ave			
City	State	Zip	
Portland	OR	97219	
Latitude		Longitude	
45.43651		122.73134	
Tracking Code		Inspection Date	
New Building		3/1/2007	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sylvania - South Classroom B.


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1997	1997	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10600	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions