

Sylvania - Technology Classroom

Mult_coc36A

Portland CC

Building Type		County	
Community_College		Multnomah	
Street			
12000 Sw 49th Ave			
City	State	Zip	
Portland	OR	97219	
Latitude		Longitude	
45.43736		122.73024	
Tracking Code		Inspection Date	
New Building		3/1/2007	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sylvania - Technology Classroom


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2004	2004	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
46394	3	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions