

Gresham Fire Station 73 Pleasant View

Mult_fir02A

City of Gresham

Building Type Fire - City	County Multnomah	
Street 2301 Sw Pleasant View		
City Gresham	State OR	Zip 97080
Latitude 45.47964	Longitude 122.46799	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Tertiary		0	0	0	0	0	0	0	0	0

Gresham Fire Station 73 Pleasant View

Final RVS Score

Final Type	Final Score
S3	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Gresham Fire Station 73 Pleasant View

Mult_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
32670	1	No	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Primary Structural Type	NE	Elevation View
			
		NW Plan Irregularity Primary	
			
W	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries