

# Portland F & R - Station 04 PSU

Mult\_fir08A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
511 SW College Street			
City	State	Zip	
Portland	OR	97201	
Latitude		Longitude	
45.50972		122.68275	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 04 PSU

## Final RVS Score

Final Type

Final Score



FEMA-154 Collapse Potential

Moderate (>1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1962	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7731		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions