

Portland F & R - Station 45 Rockwood

Mult_fir09A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
1927 SE 174th Street			
City	State	Zip	
Portland	OR	97233	
Latitude		Longitude	
45.50863		122.48513	
Tracking Code		Inspection Date	
Missed		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 45
Rockwood

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1958	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3718		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions