

Portland Fire Bureau - Maintenance And Fire Information

Mult_fir11A

City of Portland

Building Type	County
Fire - City	Multnomah
Street	
1135 SE Powell Blvd	
City	State Zip
Portland	OR 97202
Latitude	Longitude
45.50133	122.65334
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Portland Fire Bureau - Maintenance And Fire Information Service

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Portland Fire Bureau - Maintenance And Fire Information

Mult_fir11A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1983	1983	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Building On Hill or Sloped Site	
None		Internal Discontinuous Diaphram (large internal opening)	
None		Vertical Change in Structural Type (Stiff over Stiff)	
Falling Hazards		Poor Conditions	
Other: General		Cracks	
None		None	
None		None	
	W Elevation View		W Building Name
	N Secondary Structural Type		N
	N Number of Stories		NE Elevation View
 <p>PORTLAND Fire Rescue Emergency Services MAINTENANCE AND FIRE INFORMATION SERVICES HOURS 4:30 PM MON. - THUR. 5:30 PM FRI. 23-4013</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries