

Portland F & R - Station 11 Lents

Mult_fir15A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
5707 SE 92nd Avenue			
City	State	Zip	
Portland	OR	97266	
Latitude	Longitude		
45.4811	122.56892		
Tracking Code	Inspection Date		
Missed	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 11 Lents

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1928	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3580		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions