

# Portland F & R - Station 23 Lower Eastside

City of Portland

Mult\_fir23A

Building Type	County	
Fire - City	Multnomah	
Street		
2915 SE 13th Place		
City	State	Zip
Portland	OR	97202
Latitude	Longitude	
45.50185	122.65258	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 23 Lower Eastside

## Final RVS Score

Final Type      Final Score

FEMA-154 Collapse Potential

High (>10%)

No  
Planview  
Available



OregonGeology

# Portland F & R - Station 23 Lower Eastside

Mult\_fir23A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Plan Irregularities		Vertical Irregularities	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
Falling Hazards		Poor Conditions	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	