

Portland F & R - Station 24 Swan Island

Mult_fir25A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
4515 N Maryland			
City	State	Zip	
Portland	OR	97217	
Latitude		Longitude	
45.55583		122.68144	
Tracking Code		Inspection Date	
Missed		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 24 Swan Island

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1959	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6753		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions

