

# Portland F & R - Station 07 Mill Park

City of Portland

Mult\_fir26A

|                                      |                              |              |
|--------------------------------------|------------------------------|--------------|
| Building Type<br>Fire - City         | County<br>Multnomah          |              |
| Street<br>1500 SE 122nd Avenue       |                              |              |
| City<br>Portland                     | State<br>OR                  | Zip<br>97233 |
| Latitude<br>45.51256                 | Longitude<br>122.53719       |              |
| Tracking Code<br>Already Retrofitted | Inspection Date<br>9/15/2006 |              |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Portland F & R - Station 07 Mill Park

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
|            |             |

## FEMA-154 Collapse Potential

Moderate (>1%)

No  
Planview  
Available



OregonGeology

# Portland F & R - Station 07 Mill Park

Mult\_fir26A

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        |                             | 1975                     |                    |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 10090                  |                             | No                       | No                 |
| Plan Irregularities    |                             | Vertical Irregularities  |                    |
|                        |                             |                          |                    |
|                        |                             |                          |                    |
|                        |                             |                          |                    |
| Falling Hazards        |                             | Poor Conditions          |                    |
|                        |                             |                          |                    |
|                        |                             |                          |                    |
|                        |                             |                          |                    |