

Portland F & R - Station 19 Mt Tabor

City of Portland

Mult_fir28A

| | | |
|----------------------------------|------------------------------|--------------|
| Building Type Fire - City | County Multnomah | |
| Street 7301 E Burnside Street | | |
| City Portland | State OR | Zip 97215 |
| Latitude 45.52317 | Longitude 122.58757 | |
| Tracking Code Missed | Inspection Date 9/15/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Portland F & R - Station 19 Mt Tabor

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| | |

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



OregonGeology

Portland F & R - Station 19 Mt Tabor

Mult_fir28A

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1953 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 5676 | | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |