

Sauvie Island Vol RFPD 30J

Mult_fir34A

Sauvie Island RFPD

Building Type		County	
Fire - RFPD		Multnomah	
Street			
18342 NW Sauvie Island Rd			
City	State	Zip	
Portland	OR	97231	
Latitude		Longitude	
45.65655		122.83472	
Tracking Code		Inspection Date	
RVS in 2006		7/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sauvie Island Vol RFPD 30J

Final RVS Score

Final Type

Final Score

S3

2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Elevation View