

Portland F & R - Station 16 Sylvan

Mult_fir41A

City of Portland

Building Type		County	
Fire - City		Multnomah	
Street			
1715 SW Skyline Blvd			
City	State	Zip	
Portland	OR	97221	
Latitude		Longitude	
45.51076		122.73591	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Portland F & R - Station 16 Sylvan

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2002	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5830		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions