

TVF & R - Station 63 Skyline (Apparatus)

Tualatin Valley F&R

Mult_fir44A

Building Type Fire - RFPD	County Multnomah	
Street 11646 NW Skyline		
City Portland	State OR	Zip 97231
Latitude 45.60847	Longitude 122.86039	
Tracking Code RVS in 2006	Inspection Date 7/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary	C2	2.8	0	0	0	2.4	-0.4	0	0	4.8
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 63 Skyline (Apparatus)

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 63 Skyne (Apparatus)

Mult_fir44A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1972	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4600	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Elevation View	N	Elevation View
			
E	Secondary Structural Type	N	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries