

# Multnomah County RFPD 14 Springdale Station #61

Mult\_fir45A

Multnomah County RFPD 14 Aims Station #63

Building Type	County	
Fire - RFPD	Multnomah	
Street		
31727 E Historic Columbia River Hwy		
City	State	Zip
Corbett	OR	97019
Latitude	Longitude	
45.5115	122.18689	
Tracking Code	Inspection Date	
RVS in 2006	7/5/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Multnomah County RFPD 14  
Springdale Station #61

## Final RVS Score

Final Type	Final Score
RM1	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Multnomah County RFPD 14 Springdale Station #61

## Mult\_fir45A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1968	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1292	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 SE Primary Structural Type		 SW Primary Structural Type	
 N Elevation View		 Elevation View	



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries