

Portland Police Bureau NE Community Policing Cent

City of Portland

Mult_pol01A

Building Type Police - City	County Multnomah	
Street 449 NE Emerson		
City Portland	State OR	Zip 97211
Latitude 45.5623	Longitude 122.66087	
Tracking Code New Building	Inspection Date 6/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Portland Police Bureau NE
Community Policing Center

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential


Very High (100%)



OregonGeology

Portland Police Bureau NE Community Policing Center

Mult_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1997	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6762	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
Heavy Cladding (thick stone or concrete)		None	
None		None	
			
E Elevation View		E Elevation View	
			
E Falling Hazard		E Falling Hazard	
			
S Falling Hazard		NE Plan Irregularity Secondary	
			
NE Plan Irregularity Secondary		NE Plan Irregularity Secondary	
			
SE Elevation View		SW Plan Irregularity Primary	
			
SW Secondary Structural Type		SW Secondary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



SW Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries