

Portland East Precinct Community Policing Center

City of Portland

Mult_pol10A

Building Type Police - City	County Multnomah	
Street 737 SE 106th Ave		
City Portland	State OR	Zip 97216
Latitude 45.51706	Longitude 122.55436	
Tracking Code RVS in 2006	Inspection Date 7/5/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	2.4	-0.4	0	0	3.3
Tertiary		0	0	0	0	0	0	0	0	0

Portland East Precinct Community Policing Center

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Portland East Precinct Community Policing Center

Mult_pol10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Elevation View		E Primary Structural Type	
		NE Number of Stories	
			
NW Vertical Irregularity Secondary		N Vertical Irregularity Primary	
		NW Pounding Potential CONN TO GARAGE NEXT DOOR	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries