

Gresham City Police

City of Gresham

Mult_pol15A

Building Type Police - City	County Multnomah	
Street 1331 NW Eastman Pkwy		
City Gresham	State OR	Zip 97030
Latitude 45.50752	Longitude 122.43676	
Tracking Code RVS in 2006	Inspection Date 7/6/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	S2	3	-1.5	-0.5	0	0	-0.4	0	0	0.6
Tertiary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1

Gresham City Police	
Final RVS Score	
Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1979	1979	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		Internal Discontinuous Diaphragm (large internal opening)	
None		None	
Falling Hazards		Poor Conditions	
Other: Light Cladding		None	
None		None	
None		None	
			
S Elevation View		S Elevation View	
		SW Elevation View	
			
S Primary Structural Type CONC SHEAR WALLS		NW Vertical Irregularity Primary	
		SE Building Name	
		NE Secondary Structural Type	

