

# Portland Police Bureau Traffic Division

City of Portland

Mult\_pol17A

Building Type Police - City	County Multnomah	
Street 1319 SW MLKJ Blvd		
City Portland	State OR	Zip 97214
Latitude 45.51328	Longitude 122.6623	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	-1	0	-0.4	0	0	1.4
Secondary	C1	2.5	0	0	-1.2	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Portland Police Bureau Traffic  
Division

## Final RVS Score

Final Type	Final Score
C1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Portland Police Bureau Traffic Division

Mult\_pol17A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Around Entire Building		Cracks	
None		None	
None		None	
			
S	Elevation View	S	Primary Structural Type INTERIOR OF WOODSHOP NOTED ON PLAN SHOWING CIP CONCRETE FRAMING
			
W	Elevation View	E	Building Name
			
NW	Elevation View	N	Poor Condition ALSO SHOWS BASEMENT SPACE



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries