

Bridger Elementary School

Portland SD 1J

Mult_sch10A

Building Type		County	
School		Multnomah	
Street			
7910 Se Market St			
City	State	Zip	
Portland	OR	97215	
Latitude	Longitude		
45.51054	122.58218		
Tracking Code	Inspection Date		
Already Retrofitted	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary										
Tertiary										0

Bridger Elementary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

Moderate (>1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1951	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45142	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions