

Sitton Elementary School

Mult_sch106A

Portland SD 1J

Building Type		County	
School		Multnomah	
Street			
9930 N Smith St			
City	State	Zip	
Portland	OR	97203	
Latitude		Longitude	
45.59997		122.75815	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary										
Tertiary										0

Sitton Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
300		1949	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
58762	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions