

# Sunnyside Environmental School

Portland SD 1J

Mult\_sch108A

Building Type	County	
School	Multnomah	
Street		
3421 Se Salmon St		
City	State	Zip
Portland	OR	97214
Latitude	Longitude	
45.51459	122.62883	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Sunnyside Environmental School

## Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
443		1925	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
67492	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions