

# Cleveland High School

Portland SD 1J

Mult\_sch118A

Building Type		County	
School		Multnomah	
Street			
3400 Se 26th Ave			
City	State	Zip	
Portland	OR	97202	
Latitude		Longitude	
45.49856		122.63854	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Cleveland High School

## Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1447		1928	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
252885	3	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions