

Franklin High School

Portland SD 1J

Mult_sch119A

Building Type		County	
School		Multnomah	
Street			
5405 Se Woodward St			
City	State	Zip	
Portland	OR	97206	
Latitude	Longitude		
45.5023	122.60701		
Tracking Code	Inspection Date		
Already Retrofitted	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	-0.2	0	-0.4	0	0	-0.3
Secondary										
Tertiary										0

Franklin High School

Final RVS Score

Final Type

Final Score

URM

-0.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1404		1915	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
294878	3	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions