

# Cherry Park Elementary School

Mult\_sch13A

David Douglas SD 40

Building Type	County	
School	Multnomah	
Street		
1930 SE 104th Ave		
City	State	Zip
Portland	OR	97216
Latitude	Longitude	
45.5089	122.55565	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Cherry Park Elementary School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)
-------------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Cherry Park Elementary School

Mult\_sch13A

Enrollment 452	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built 1950
Total Area (square ft) 54150	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: E Shaped None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards Unreinforced Chimneys Other: Brick Veneer None		Poor Conditions None None None	
			
W Secondary Structural Type		W Elevation View	
			
N Plan Irregularity Primary		E Elevation View	
			
E Pounding Potential		E Plan Irregularity Primary	
			
SE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Cherry Park Elementary School

Mult\_sch13A



SE Vertical Irregularity Primary



SW Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Cherry Park Elementary School

Mult\_sch13B

David Douglas SD 40

Building Type	County
School	Multnomah
Street	
1930 SE 104th Ave	
City	State Zip
Portland	OR 97216
Latitude	Longitude
45.50886	122.55504
Tracking Code	Inspection Date
RVS in 2006	7/7/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cherry Park Elementary School

## Final RVS Score

Final Type	Final Score
W2	3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Cherry Park Elementary School

Mult\_sch13B

Enrollment 452	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built 1970
Total Area (square ft) 54150	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Elevation View			