

Hall Elementary School

Gresham-Barlow SD 10J

Mult_sch131A

Building Type		County	
School		Multnomah	
Street			
2505 Ne 23rd St			
City	State	Zip	
Gresham	OR	97030	
Latitude		Longitude	
45.51451		122.40642	
Tracking Code		Inspection Date	
Missed		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hall Elementary School

Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
509		1980	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
58804		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions