

Lynch View Elementary School

Centennial SD 28J

Mult_sch152A

Building Type	County
School	Multnomah
Street	
1546 Se 169th Pl	
City	State Zip
Portland	OR 97233
Latitude	Longitude
45.51124	122.48818
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lynch View Elementary School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Lynch View Elementary School

Mult_sch152A

Enrollment 493	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1960		
Total Area (square ft) 49151	Number of Stories 1	Basement	Pounding Potential Yes		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes			
Torsion: Eccentric Stiffness		None			
None		None			
Falling Hazards		Poor Conditions			
Other: Ornamental Hazard Over Exit		None			
None		None			
None		None			
	W Primary Structural Type		W Plan Irregularity Primary		NW Vertical Irregularity Primary
	SW Vertical Irregularity Primary		S Elevation View		SE Elevation View
	S Falling Hazard		E Falling Hazard		E Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



NE Plan Irregularity Secondary

