

Ron Russell Middle School

David Douglas SD 40

Mult_sch155A

Building Type	County	
School	Multnomah	
Street		
3955 SE 112th St		
City	State	Zip
Portland	OR	97266
Latitude	Longitude	
45.49411	122.54897	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ron Russell Middle School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ron Russell Middle School

Mult_sch155A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
806		2005	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site