

Lynch Meadows Elementary School

Centennial SD 28J

Mult_sch156A

Building Type	County
School	Multnomah
Street	
18009 SE Brooklyn St	
City	State Zip
Portland	OR 97236
Latitude	Longitude
45.50153	122.47746
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Lynch Meadows Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential


Moderate (>1%)



OregonGeology

Lynch Meadows Elementary School

Mult_sch156A

Enrollment 533	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1970
Total Area (square ft) 53836	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
S Vertical Irregularity Primary	S Primary Structural Type	S Primary Structural Type	
			
SE Vertical Irregularity Primary	E Secondary Structural Type	E Falling Hazard	
			
N Secondary Structural Type	N Plan Irregularity Primary	E Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lynch Meadows Elementary School

Mult_sch156A



W Elevation View



SW Elevation View

Lynch Meadows Elementary School

Centennial SD 28J

Mult_sch156B

Building Type	County
School	Multnomah
Street	
18009 SE Brooklyn St	
City	State Zip
Portland	OR 97236
Latitude	Longitude
45.50201	122.47811
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lynch Meadows Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Lynch Meadows Elementary School

Mult_sch156B

Enrollment 533	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built 1980
Total Area (square ft) 53836	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



Elevation View



NW Plan Irregularity Primary



Elevation View



S Other
DIAPHRAGM HOLE



W Other
A TO B CONN



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries