

# Helensview High School

Multnomah ESD

Mult\_sch159A

Building Type	County	
School	Multnomah	
Street		
8678 NE Sumner St		
City	State	Zip
Portland	OR	97220
Latitude	Longitude	
45.56123	122.57433	
Tracking Code	Inspection Date	
RVS in 2006	6/29/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Helensview High School

## Final RVS Score

Final Type	Final Score
C2	0.9

## FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Helensview High School

Mult\_sch159A

Enrollment 186	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built 1960
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Lateral-Force-Resistance		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
NE Plan Irregularity Primary	NE Plan Irregularity Primary	NE Plan Irregularity Primary	
			
NW Elevation View	NW Vertical Irregularity Primary	NW Elevation View	
			
NW Falling Hazard	SW Plan Irregularity Primary	SW Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Helensview High School

Mult\_sch159A



SE Seismic Upgrade



SE Seismic Upgrade



E Primary Structural Type



E Building Name



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries