

Pioneer Special Education Program

Portland SD 1J

Mult_sch163A

Building Type	County	
School	Multnomah	
Street		
2704 SE 71st Ave		
City	State	Zip
Portland	OR	97206
Latitude	Longitude	
45.50313	122.58888	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: High										Pioneer Special Education Program		
FEMA 154 Rapid Visual Screening Score Card												
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7	W2	0.5
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5	FEMA-154 Collapse Potential	
Tertiary										0	Moderate (>1%)	



Pioneer Special Education Program

Mult_sch163A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
S	Vertical Irregularity Primary	NW	Falling Hazard
			
S	Plan Irregularity Primary	S	Plan Irregularity Primary
			
S	Primary Structural Type THIS IS CMU BLOCK	N	Pounding Potential
			
N	Elevation View	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries