

Alice Ott Middle School

Mult_sch22A

David Douglas SD 40

Building Type	County	
School	Multnomah	
Street		
12500 Se Ramona St		
City	State	Zip
Portland	OR	97236
Latitude	Longitude	
45.47957	122.53504	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Alice Ott Middle School

Final RVS Score

Final Type Final Score
C2 -0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Alice Ott Middle School

Mult_sch22A

Enrollment 697	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 1930		
Total Area (square ft) 76911	Number of Stories 1	Basement	Pounding Potential Yes		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes			
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)			
None		None			
Falling Hazards		Poor Conditions			
Other: Ornamental Hazard Over Exit		None			
Other: Brick Veneer		None			
None		None			
	N Other CONN TO NEWER SECT - SEIS JT ABOUT 2"		N Falling Hazard		W Basement
	SW Elevation View				



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Alice Ott Middle School

David Douglas SD 40

Mult_sch22B

Building Type	County	
School	Multnomah	
Street		
12500 Se Ramona St		
City	State	Zip
Portland	OR	97236
Latitude	Longitude	
45.47914	122.53475	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Alice Ott Middle School

Final RVS Score

Final Type Final Score
W2 0.9

FEMA-154 Collapse Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Alice Ott Middle School

Mult_sch22B

Enrollment 697	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 1960
Total Area (square ft) 76911	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
SE Elevation View		SE Primary Structural Type	W Pounding Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Alice Ott Middle School

David Douglas SD 40

Mult_sch22C

Building Type	County	
School	Multnomah	
Street		
12500 Se Ramona St		
City	State	Zip
Portland	OR	97236
Latitude	Longitude	
45.47936	122.53433	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Alice Ott Middle School

Final RVS Score

Final Type Final Score
RM1 1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment 697	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 1950
Total Area (square ft) 76911	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 E Primary Structural Type			

