

# Sam Barlow High School

Gresham-Barlow SD 10J

Mult\_sch27A

Building Type	County	
School	Multnomah	
Street		
5105 Se 302nd Ave		
City	State	Zip
Gresham	OR	97080
Latitude	Longitude	
45.48538	122.35388	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sam Barlow High School

## Final RVS Score

Final Type	Final Score

## FEMA-154 Collapse Potential

High (>10%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sam Barlow High School

Mult\_sch27A

Enrollment 1900	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built
Total Area (square ft) 287308	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site		
			
S	General Site	S	General Site
			
S	General Site		
			
S	General Site	S	General Site
			
S	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries