

Building Type	County	
School	Multnomah	
Street		
10531 SW Capitol Hwy		
City	State	Zip
Portland	OR	97219
Latitude	Longitude	
45.44924	122.72547	
Tracking Code	Inspection Date	
Already Retrofitted	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	PC1	2.6	0	0	0	0	-0.4	0	0	2.2
Tertiary										0

Markham Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

Moderate (&gt;1%)

No  
Planview  
Available



# Markham Elementary School

Mult\_sch31A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
396	1950	1950	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
86362	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: H Shaped		Steps in Elevation View: Single Change	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys			
			
S	General Site	S	General Site
S	General Site	S	General Site
			
S	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries