

Head Start Sacajawea

Mult_sch39A

Portland SD 1J

Building Type		County	
School		Multnomah	
Street			
4800 NE 74th Ave			
City	State	Zip	
Portland	OR	97218	
Latitude		Longitude	
45.55821		122.58708	
Tracking Code		Inspection Date	
RVS in 2006		6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary										0

Head Start Sacajawea

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
625		1952	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: U shaped	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



NW Seismic Upgrade



NW Elevation View



N Falling Hazard



NE Plan Irregularity Primary



SE Elevation View



SE Vertical Irregularity Primary