

Da Vinci Middle School

Portland SD 1J

Mult_sch57A

Building Type	County	
School	Multnomah	
Street		
2508 Ne Everett		
City	State	Zip
Portland	OR	97232
Latitude	Longitude	
45.52468	122.6401	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Secondary										
Tertiary										0

Da Vinci Middle School

Final RVS Score

Final Type	Final Score
C2	-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Da Vinci Middle School

Mult_sch57A

Enrollment 380	Year Built (Field Verified) 1928	Year Built (Alt. Source) 1920	Est. Decade Built 1920
Total Area (square ft)	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped Out of Plane Lateral-Force-Resistance Elements None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Internal Discontinuous Diaphragm (large internal opening) None	
Falling Hazards Other: Heavy cornice or other overhead decoration Other: Brick Veneer None		Poor Conditions None	
			
NE Elevation View	E Vertical Irregularity Primary	SE Falling Hazard	
			
SW Elevation View	N Falling Hazard	N Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries