

Building Type School	County Multnomah	
Street 1151 SW Vermont St		
City Portland	State OR	Zip 97219
Latitude 45.47722	Longitude 122.68977	
Tracking Code Structural Engineering Report	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary										
Tertiary										0

Wilson High School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (&gt;10%)

No  
Planview  
Available



Oregon Geology

# Wilson High School

Mult\_sch64A

Enrollment 1632	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built
Total Area (square ft) 326062	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries