

# Ainsworth Elementary School

Mult\_sch70A

Portland SD 1J

Building Type		County	
School		Multnomah	
Street			
2425 Sw Vista Ave			
City	State	Zip	
Portland	OR	97201	
Latitude	Longitude		
45.50975	122.69952		
Tracking Code	Inspection Date		
Already Retrofitted	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	-0.2	0	0	0	0	0.1
Secondary										
Tertiary										0

Ainsworth Elementary School

## Final RVS Score

Final Type

Final Score

URM

0.1

FEMA-154 Collapse Potential

Moderate (>1%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
491		1912	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
57593	3	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions