

Building Type	County	
School	Multnomah	
Street		
9325 N Van Houten Ave		
City	State	Zip
Portland	OR	97203
Latitude	Longitude	
45.59029	122.72388	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary										
Tertiary										0

Clarendon Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (&gt;10%)

No  
Planview  
Available



OregonGeology

# Clarendon Elementary School

Mult\_sch71A

Enrollment 325	Year Built (Field Verified) 1970	Year Built (Alt. Source) 1970	Est. Decade Built
Total Area (square ft) 42958	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	