

## Clark Elementary School

Mult\_sch72A

Portland SD 1J

Building Type		County	
School		Multnomah	
Street			
1231 Se 92nd Ave			
City	State	Zip	
Portland	OR	97216	
Latitude	Longitude		
45.51364	122.56975		
Tracking Code	Inspection Date		
Already Retrofitted	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Clark Elementary School

## Final RVS Score

Final Type

Final Score

URM

-0.1

FEMA-154 Collapse Potential

Moderate (&gt;1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
500		1955	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
50595	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions