

Duniway Elementary School

Portland SD 1J

Mult_sch74A

Building Type	County	
School	Multnomah	
Street		
7700 Se Reed College Pl		
City	State	Zip
Portland	OR	97202
Latitude	Longitude	
45.46858	122.62852	
Tracking Code	Inspection Date	
Already Retrofitted	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Duniway Elementary School

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Moderate (>1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
443		1926	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
67492	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions