

# Kellogg Middle School

Portland SD 1J

Mult\_sch87A

Building Type		County	
School		Multnomah	
Street			
3330 Se 69th			
City	State	Zip	
Portland	OR	97206	
Latitude		Longitude	
45.49873		122.59166	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Kellogg Middle School

## Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
481		1913	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
94592	3	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions