

Laurelhurst Elementary School

Mult_sch90A

Portland SD 1J

Building Type		County	
School		Multnomah	
Street			
840 Ne 41st Ave			
City	State	Zip	
Portland	OR	97232	
Latitude	Longitude		
45.52913	122.61984		
Tracking Code	Inspection Date		
Structural Engineering Report	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary										
Tertiary										0

Laurelhurst Elementary School

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
581		1923	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
46204	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions