

Lee Elementary School

Portland SD 1J

Mult_sch91A

Building Type		County	
School		Multnomah	
Street			
2222 Ne 92nd Ave			
City		State	Zip
Portland		OR	97220
Latitude		Longitude	
45.53802		122.56755	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary										
Tertiary										0

Lee Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
309		1953	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
73701	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions