

# Lent Elementary School

Mult\_sch92A

Portland SD 1J

|                               |                 |           |  |
|-------------------------------|-----------------|-----------|--|
| Building Type                 |                 | County    |  |
| School                        |                 | Multnomah |  |
| Street                        |                 |           |  |
| 5105 Se 97th Ave              |                 |           |  |
| City                          | State           | Zip       |  |
| Portland                      | OR              | 97266     |  |
| Latitude                      | Longitude       |           |  |
| 45.48544                      | 122.56403       |           |  |
| Tracking Code                 | Inspection Date |           |  |
| Structural Engineering Report | 9/15/2006       |           |  |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | -2         | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 0.9       |
| Secondary |      |             |            |            |          |            |        |        |        |           |
| Tertiary  |      |             |            |            |          |            |        |        |        | 0         |

Lent Elementary School

## Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
| 366                    |                             | 1949                     |                    |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 76478                  | 1                           | No                       | No                 |

|                     |                         |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
|                     |                         |
|                     |                         |
|                     |                         |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
|                 |                 |
|                 |                 |
|                 |                 |