

West Valley Community Hospital - Dallas

Polk_hos01A

Pacific Health Horizons NFP

Building Type		County	
Hospital		Polk	
Street			
525 SE Washington St			
City	State	Zip	
Dallas	OR	97338	
Latitude		Longitude	
44.91878		123.31031	
Tracking Code		Inspection Date	
New Building		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Valley Community Hospital - Dallas

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1972	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
123275	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Primary Structural Type



E Plan Irregularity Primary



E General Site



S Vertical Irregularity Primary