

Independence Police Department

City of Independence

Polk_pol03A

Building Type Police - City	County Polk	
Street 240 Monmouth St		
City Independence	State OR	Zip 97351
Latitude 44.85143	Longitude 123.1865	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1

Independence Police Department

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Independence Police Department

Polk_pol03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1972	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
19602	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Plan Irregularity Primary		NE Vertical Irregularity Primary	
		NW General Site	